



DANGER - WORK AT HEIGHT / FALLING OBJECTS

DANGER

Use at scaffold, EWP, ladder and overhead work exclusion zones.

NO UNAUTHORISED ENTRY BELOW OR WITHIN THE CONTROLLED WORK ZONE

KEEP OUT

- Do not pass under scaffold, EWP, ladders or overhead work.
- Obey barriers, spotters and marked exclusion zones.
- Hard hats are required where designated by the site controls.
- Residents, visitors and children must not enter the work zone.
- Never move or alter barriers, scaffold tags, edge protection or access controls.

WORKER CONTROLS

- Use the approved access method and inspect equipment before use.
- Secure tools and materials against falling. Do not throw materials from height.
- Maintain edge protection and fall controls required by the JSEA/SSSP.
- Set and maintain a suitable exclusion zone below overhead work.
- Stop work immediately if the exclusion zone is breached or weather makes the task unsafe.
- Remove or secure ladders and access equipment when the site is unattended.