



# CONTROLLED AREA - DUST / LEAD / ASBESTOS / CHEMICALS

CONTROLLED AREA

Display only when relevant to the task and identified in the JSEA or project controls.

**DO NOT ENTER UNLESS AUTHORISED AND THE REQUIRED PPE / RPE CONTROLS ARE IN PLACE**

## DUST / SILICA

- Use extraction, wet methods or containment specified for the task.
- Prevent dust migration into occupied rooms and common areas.
- Keep others outside the controlled area until clean-up is complete.

## LEAD-BASED PAINT

- Follow lead-specific containment, hygiene and waste controls.
- No dry uncontrolled sanding or contamination of occupied areas.
- Wash hands before eating, drinking or leaving the work area.

## ASBESTOS / UNKNOWN ACM

- STOP WORK if suspect or unidentified material is disturbed or exposed.
- Do not cut, sand, drill or remove suspect ACM unless authorised under the project asbestos controls.
- Isolate the area and notify the site lead/client immediately.

## PAINTS / SOLVENTS / CHEMICALS

- Keep lids closed and substances secured from residents and children.
- Follow SDS requirements for ventilation, ignition sources and PPE.
- Store and dispose of waste in accordance with project and product requirements.